

Global Parts Order Processing
Material Safety Data Sheet
KLINTBERG & WAY AB

C H R Y S L E R
HAZARD COMMUNICATION SHEET

303970 DRAFT PART/COMMTY CD: 68218657GA
PREPARATION DATE: 08-09-13 STNDRD: N/AV SUPPLIER: 90117 MFGR: 03500
OSHA HAZ: YES HAZWOPER HAZ: YES CONS PROD/HAZ SUB: YES

*** SECTION 01 - PRODUCT INFORMATION ***

MFG BY: PART SALES & SERVICE FCA US LLC
26311 LAWRENCE AVE CENTERLINE MI 48015
EMERGENCY PHONE: 248-512-8002 AFTER HOURS: 248-576-8888
DIST BY: PART SALES & SERVICE FCA US LLC
26311 LAWRENCE AVE CENTERLINE MI 48015
EMERGENCY PHONE: 248-512-8002 AFTER HOURS: 248-576-8888
FCA US LLC INDUSTRIAL HYGIENE: 248-512-8260 AFTER HOURS: 248-576-8888
BRAND NAME: MOPAR SYNTHETIC GEAR OIL 75W-140
MFG ID : 228C8318
DESCRIPTION: LUBE AXEL

*** SECTION 02 - INGREDIENTS ***

HAZARDOUS INGREDIENTS: PERCENT
COMM NAME / CAS NO & CHEM NAME: BY WGT OSHA ACGIH CHRYS UNITS NOTATIONS
EXISTING INGREDIENTS
PARAFFINIC PROCESS OIL 1-5 W 5 5 5 MG/M3
064742-54-7A DISTILLATES (PETROLE L N/AP 10 10
HYDROCARBON POLYMER 60-100 W N/AV N/AV N/AV N/AV
031533-58-1 HYDROCARBON POLYMER
UNSATURATED POLY CARBOXYLIC ACID 10-30 W N/AV N/AV N/AV N/AV
052617-00-8C POLYCARBOXYLIC ACID
GENERIC DESC: POLYMER(S), ESTER(S), PETROLEUM OIL, AMINE(S).

*** SECTION 03 - PHYSICAL DATA ***

BOILING POINT : N/AV F SOLUB IN WATER: NEGLIGIBLE (< 0.1%)
VAPOR PRESSURE: 0 MM HG AT 68 F EVAP. RATE: N/AV REF: N/AV
VAPOR DENSITY : N/AV SPECIFIC GRAVITY: 0.870 AT N/AV
PH AT FULL STRENGTH: N/AV PH AT REC. DILUT: N/AV
%VOLATILE BY VOL : N/AV VOLATILE ORGANIC COMP: N/AV N/AV
ODOR THRESHOLD: N/AV PPM FOR % POPULATION
FREEZING POINT: N/AV COEFF. OF WATER/OIL DIST: N/AV
APPEARANCE & ODOR: APPEARANCE: PALE....., COLOR: YELLOW....., STATE:
LIQUID..... AND ODOR: MILD.....

*** SECTION 04 - FIRE AND EXPLOSION DATA ***

FLASH POINT: 329 F N/AV IGN TEMP: 669 F LEL: N/AV UEL: N/AV

**Global Parts Order Processing
Material Safety Data Sheet
KLINTBERG & WAY AB**

SPECIAL FIRE & EXPLOSION HAZARDS:

DO NOT ALLOW PRODUCT OR RUNOFF WATER TO ENTER STORM OR SANITARY SEWERS, GROUND WATER, OR SOIL. RELEASES TOXIC FUMES OR GASES MAY PRODUCE TOXIC THERMAL DECOMPOSITION PRODUCTS.

EXTINGUISHING MEDIA:

WATER FOG, FOAM, DRY CHEMICAL, CARBON DIOXIDE AND DO NOT USE WATER IN STRAIGHT STREAMS.

SPECIAL FIREFIGHTING PROCEDURES:

DO NOT ALLOW PRODUCT OR RUNOFF WATER TO ENTER STORM OR SANITARY SEWERS, GROUND WATER, OR SOIL. EVACUATE PERSONNEL FROM AREA. USE SELF-CONTAINED BREATHING APPARATUS WITH A FULL FACEPIECE OPERATED IN PRESSURE DEMAND OR OTHER POSITIVE PRESSURE MODE. USE PROTECTIVE CLOTHING. USE SELF-CONTAINED BREATHING APPARATUS. USE WATER TO COOL FIRE EXPOSED CONTAINERS.

SENSITIVE TO MECHANICAL IMPACT?: N/AV SENSITIVE TO STATIC DISCHARGE?: N/AV

HAZARDOUS COMBUSTION PRODUCTS:

ALDEHYDES, OXIDES OF SULFUR AND CARBON MONOXIDE AND CARBON DIOXIDE OR SMOKE, IRRITATING FUMES.

FLAME PROJECTION: N/AP

*** SECTION 05 - HEALTH HAZARD DATA ***

EFFECTS OF OVEREXPOSURE - ACUTE & CHRONIC:

<<---INGESTION--->> NO KNOWN EFFECTS. HOWEVER, INGESTION IS NOT RECOMMENDED. <<---EYE CONTACT--->> MAY PRODUCE THE FOLLOWING: MINOR IRRITATION. <<---SKIN CONTACT--->> MAY PRODUCE THE FOLLOWING: IRRITATION AND INJECTION OF OIL INTO THE SKIN MAY CAUSE PERMANENT LOCAL SKIN DAMAGE. <<---INHALATION--->> MAY PRODUCE THE FOLLOWING: IRRITATION OF UPPER RESPIRATORY TRACT.

EMERGENCY FIRST AID PROCEDURES:

<<---INGESTION--->> IF CONDITION PERSISTS, CONSULT A PHYSICIAN. <<---EYE CONTACT--->> RINSE EYES IMMEDIATELY WITH LARGE AMOUNTS OF WATER, OCCASIONALLY LIFTING BOTH UPPER AND LOWER LIDS. CONTINUE FOR 15 MINUTES. IF CONDITION PERSISTS, CONSULT A PHYSICIAN. <<---SKIN CONTACT--->> WASH WITH SOAP AND WATER. IF INJECTED UNDER THE SKIN, REGARDLESS OF APPEARANCE OF THE WOUND OR ITS SIZE, CONTACT A PHYSICIAN IMMEDIATELY. IF CONDITION PERSISTS, CONSULT A PHYSICIAN. <<---INHALATION--->> REMOVE TO FRESH AIR AT ONCE. ARTIFICIAL RESPIRATION IF BREATHING HAS STOPPED. CARDIAC RESUSCITATION IF INDICATED. IF CONDITION PERSISTS, CONSULT A PHYSICIAN.

*** SECTION 06 - REACTIVITY DATA ***

STABILITY: STABLE

CONDITIONS TO AVOID:

CARBON MONOXIDE AND CARBON DIOXIDE HEAT OR SPARKS OR OPEN FLAME AND KEEP AWAY FROM WELDING PROCESSES.

MATERIALS TO AVOID:

STRONG OXIDIZING AGENTS.

Global Parts Order Processing
Material Safety Data Sheet
KLINTBERG & WAY AB

HAZARDOUS POLYMERIZATION: WILL NOT OCCUR
POLYMERIZATION CONDITIONS TO AVOID:

POLYMERIZATION WILL NOT OCCUR.

HAZARDOUS DECOMPOSITION PRODUCTS:

THERMAL DECOMPOSITION MAY PRODUCE THE FOLLOWING: CARBON MONOXIDE AND CARBON DIOXIDE, OXIDES OF SULFUR, IRRITATING FUMES OR SMOKE.

*** SECTION 07 - SPILL OR LEAK PROCEDURES ***

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED:

ELIMINATE ALL IGNITION SOURCES (FLAMES, HOT SURFACES AND ELECTRICAL, STATIC OR FRICTIONAL SPARKS). AVOID BREATHING VAPORS. PROVIDE ADEQUATE VENTILATION. WEAR PROTECTIVE CLOTHING. ABSORB ON AN INERT MATERIAL AND REMOVE WITH NON-SPARKING TOOLS. DISCARD INTO SEALED CONTAINERS FOR DISPOSAL.

WASTE DISPOSAL METHODS:

DISPOSE OF IN A MANNER CONSISTENT WITH STATE, PROVINCIAL, LOCAL, AND FEDERAL REGULATIONS.

*** SECTION 08 - SPECIAL PROTECTION ***

RESPIRATORY PROTECTION:

NO SPECIAL PROTECTION NEEDED UNDER NORMAL CONDITIONS.

VENTILATION TYPE:

LOCAL EXHAUST VENTILATION.. GOOD GENERAL VENTILATION. THIS EQUIPMENT MAY BE ADEQUATE.

PROTECTIVE GLOVES:

RECOMMENDED. NEOPRENE GLOVES, NITRILE RUBBER GLOVES OR POLYVINYL ALCOHOL (PVA) GLOVES.

EYE PROTECTION:

RECOMMENDED. SAFETY GLASSES.

OTHER PROTECTIVE EQUIPMENT:

APRON (SAME MATERIAL AS GLOVES) AND CLOTHING (SAME MATERIAL AS GLOVES).. IF PROTECTIVE EQUIPMENT OR VENTILATION IS NEEDED, THIS IS THE RECOMMENDED TYPE TO USE..

*** SECTION 09 - SPECIAL PRECAUTIONS ***

PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE:

STORE IN A COOL, DRY PLACE. STORE AWAY FROM DIRECT SUNLIGHT. KEEP FROM HEAT, SPARK OR OPEN FLAMES. BOND AND GROUND ALL CANS, DRUMS, MIXERS ETC. TO PREVENT STATIC SPARKS. TAKE "NO SMOKING" PRECAUTIONS. USE WITH ADEQUATE VENTILATION. KEEP CONTAINER TIGHTLY CLOSED WHEN NOT IN USE. CONTAINERS OF THIS MATERIAL MAY BE HAZARDOUS WHEN EMPTIED, SINCE EMPTIED CONTAINERS RETAIN PRODUCT RESIDUES (VAPOR, LIQUID, AND/OR SOLID). COMBUSTIBLE.

OTHER PRECAUTIONARY MEASURES:

DO NOT SMOKE OR EAT WHEN HANDLING THIS SUBSTANCE; WASH THOROUGHLY AFTER USING. AVOID BREATHING VAPOR. AVOID EYE CONTACT. AVOID PROLONGED OR REPEATED

33723000
s63929m

**Global Parts Order Processing
Material Safety Data Sheet
KLINTBERG & WAY AB**

den 11 oktober 2018
04:17

SKIN CONTACT. AVOID INGESTION. REACTS WITH OXIDIZERS. REMOVE CONTAMINATED CLOTHING AND LAUNDRY BEFORE REUSE. MAINTAIN GOOD HOUSEKEEPING AND HYGIENIC PRACTICES. COMBUSTIBLE.

*** SECTION 10 - WASTE LABELING INFORMATION ***

DOT LABELING INFORMATION (49 CFR 100-199)

ID#: N/AP ERG#: HAZARD CLASS - PRMY: N/AP PACKING GROUP: N/AP

NOT HAZARDOUS PER DOT REGULATIONS

RCRA INFORMATION (40 CFR 122-124, 260-265)

INFORMATION UNAVAILABLE AT THIS TIME